



7100 Technology Drive
West Melbourne, FL 32904
1-800-422-6281

Service Bulletin

BKSB-1019
Issue Date 11-12-03

Issue: DPH Firmware update to allow user selectable NAC and Code Guard between analog, digital and mixed mode channels.

Affected Models: All DPH models

Recommended Action: Upgrade firmware to Rev. 2F2383C1. It is recommended by BK Radio that this upgrade be performed on all DPH flash programmable radios with a serial number below 03380001.

(Please note: This program will validate the software revision level within the unit before writing any information. The update will only be written if required.)

Parts and Equipment Requirements:

- 1- LAA0725 Programming Cable
- 1- Software Patch from RELM.com

Procedure:

1. Verify the firmware revision installed in your DPH by pressing and holding the "1" button. Radios programmed with the current revision as of the date of this notice will display 2F2383C1.
2. Download and run patch (*DPH_Update1.zip*) from BK Radio service site <http://www.relm.com/Utility/>