



7100 Technology Drive
West Melbourne, FL 32904
1-800-422-6281

Service Bulletin

BKSB-1054
Issue Date 5/31/2018



Issue: RES compatibility issues with firmware 5.5.X and 5.6.0.

Importance: A computer with 5.5.X RES cannot read a radio with 5.6.0 firmware.

Affected Models: KNG-Pxxx, KNG2-Pxxx, KNG-Mxxx

Recommended Action: Update to RES 5.6.0 before installing 5.6.0 firmware.

Firmware Version	RES Version	5.6.0x	5.5.0x	5.4.0x	5.3.0x
	5.6.0x **	R/W	R	R	R
5.5.X	R/W*	R/W	R	R	

*** If the radio was written previously with a newer version of RES, older versions of RES will no longer be able to read it.
You can overwrite the newer codeplug with an older version of RES**

**** Versioning scheme for RES changed in the 5.6.0 release to better match firmware revisions**