



7100 Technology Drive  
 West Melbourne, FL 32904  
 1-800-422-6281

# Service Bulletin

BKSB-1071  
 Issue Date: 01/06/2022



**Issue:** Resolves potential Apache “log4j” vulnerability and the incompatibility issue with comma/decimal internationalization settings in Windows.

**Importance:** High

**Affected Models:** All KNG-Pxxx, KNG2-Pxxx, KNG-Mxxx, KAA0660, KAA0670, and BKR5000 models that uses RES version 5.8.14 or older.

**\*\*\* Does not include KNG-xxxS models \*\*\***

**Recommended Action:** Update the RES Editor to Version 5.8.17.

## Software Download

The software editor P/N BKR0733-5.8.17 can be downloaded from the BK Technologies Website at: <https://bktechnologies.com/service-portal/products>

1. Select “KNG Digital Radios” or “BKR5000 Digital Radios” from the Product Support – Software & Firmware Page
2. Select the respective Model
3. From the “Firmware & Software” Page, select the “Software” Tab at the top of the page

Firmware & Patches   **Software**   Drivers Etc..

Release Date	Revision Number	Part Number	Release Notes	Software
2021-03-19	5.8.14	BKR0733-5.8.14 (CD) BKR0733-5.8.14-USB (USB)	Release Notes	Download
2020-11-30	5.8.9	BKR0733-5.8.9 (CD) BKR0733-5.8.9-USB (USB)	Release Notes	Download
2020-10-08	5.8.8	BKR0733-5.8.8 (CD) BKR0733-5.8.8-USB (USB)	Release Notes	Download

4. Select “Download”
5. Enter the software Serial Number and select [Continue].
6. Follow the prompts