



Service Bulletin
RSB-0001
Issue Date 9-13-05

Issue: RP Series belt-clips breaking

Affected Models: RP16 Series, RP99 Series, RP3000 Series and RP3600 Series.

Recommended Action: Provide a more robust belt-clip and unify belt-clip part numbers. RELM will provide two more robust belt-clips.

BLTCLPRPL – Belt clip, battery mount, RP long.

This will be the new standard belt-clip to be used on the RP16 and RP99, RP3000 and RP3600 Series.

BLTCLPRPS – Belt clip, battery mount, RP short. This will be the replacement belt-clip for all RP3000 Series radios purchased with the serial number 04DXX4XXXX (serial numbers are located on the FCC label on the back of each radio) with the old style charger. These radios will have the shallow well charger and will only accommodate the BLTCLPRPS short belt-clip.